

San Ramon Valley Fire Protection District

Unofficial Incident Report

Amendments

Amended By 183 - Eubanks Kathleene Senior Office 02/05/2010
Assistant

Incident Reviewed By

Reviewer 183 - Eubanks Kathleene Senior Office Assistant
Date 02/05/2010

Incident

Incident # 2010-0000436-000
Incident Type 111 - Building fire
Station 31
Address 168 JOAQUIN DR
City, State ZipCode DANVILLE, CA 94526
Location 6 - Directions
Mutual Aid N - None
Entry-Alarm Time 00:00:38
Alarm Date/Time 01/22/2010 08:34:41
Arrival Date/Time 01/22/2010 08:39:58
Alarm-Arrival Time 00:05:17
Entry-Arrival Time 00:05:55
Cleared Date/Time 01/22/2010 14:14:01
Total Incident Time 05:40:27
Shift C
Alarms 2
District 31001
Action Taken1 11 - Extinguishment by fire service personnel
Property Loss \$200,000.00
Content Loss \$50,000.00
Property Value \$485,000.00
Content Value \$100,000.00
Property Use 419 - 1 or 2 family dwelling

Resources

2010-0000436-000

Unit: 3100

Unit Type	92 - Chief officer car
Dispatch Date/Time	01/22/2010 08:55:08
Enroute Date/Time	01/22/2010 08:56:40
Reflex Time	00:01:32
Arrival Date/Time	01/22/2010 09:04:17
Travel Time	00:07:37
Response Time	00:09:09
Priority Arrival	Code 2
Cleared Date/Time	01/22/2010 09:25:31
Total Unit Time	00:30:23
Unit Report By	303 - Price Richard Fire Chief
Action Taken1	92 - Standby
From Quarters	No
Narrative	No action taken.

Personnel (1) - Unit: 3100

Name	303 - Price Richard Fire Chief
------	--------------------------------

Unit: 3101

Unit Type	92 - Chief officer car
Dispatch Date/Time	01/22/2010 08:47:18
Enroute Date/Time	01/22/2010 08:47:22
Reflex Time	00:00:04
Priority Enroute	Code 2
Priority Arrival	Code 2
Cleared Date/Time	01/22/2010 13:26:17
Total Unit Time	04:38:59
Unit Report By	116 - Hart Steven Assistant Chief
Action Taken1	70 - Assistance, other
From Quarters	No
Narrative	I responded to see if I could be of assistance to the IC. Checked in with the IC and my assistance was not needed. I met with the homeowners and briefed them on our operations. I also directed EMS Officer Eberle to take some pictures.

Personnel (1) - Unit: 3101

Name	116 - Hart Steven Assistant Chief
------	-----------------------------------

Unit: 3102

Unit Type	92 - Chief officer car
Dispatch Date/Time	01/22/2010 08:51:25
Enroute Date/Time	01/22/2010 08:51:28
Reflex Time	00:00:03
Priority Enroute	Code 2
Priority Arrival	Code 2
Cleared Date/Time	01/22/2010 13:26:21
Total Unit Time	04:34:56
Unit Report By	317 - Collins Bryan Assistant Chief
Action Taken1	73 - Provide manpower
From Quarters	Yes
Narrative	3102 was dispatched to this incident at 08:51 hours. I responded from quarters (1500 Bollinger Canyon Road San Ramon). My dispatch response was Code 2 and arrival response was Code 2. I arrived at the scene checked in with the IC and assisted the Incident Safety Officer prior to clearing the incident.

Personnel (1) - Unit: 3102

Name	317 - Collins Bryan Assistant Chief
------	-------------------------------------

Unit: 3113

Unit Type	92 - Chief officer car
Dispatch Date/Time	01/22/2010 08:44:30
Enroute Date/Time	01/22/2010 08:44:34
Reflex Time	00:00:04
Priority Enroute	Code 3
Arrival Date/Time	01/22/2010 08:47:31
Travel Time	00:02:57
Response Time	00:03:01
Priority Arrival	Code 3
Cleared Date/Time	01/22/2010 09:05:29
Total Unit Time	00:20:59
Unit Report By	121 - Picard Michael Battalion Chief
Action Taken1	73 - Provide manpower
From Quarters	Yes
Narrative	3113 was dispatched to this incident at 08:44 hours. 3113 arrived on scene at 08:47 hours. 3113 dispatch response was Code 3 from Admin and arrival response was Code 3. The primary task performed by 3113 was to provide manpower.

Unit: 3113

3113 responded to a working structure fire from Administration building. Upon arrival I assisted B31/IC as overhead position. 3113 was assigned District coverage from scene. 3113 remained on scene assisting then went to 31 to cover from Dispatch center. 3113 brought some food back to the scene and did face to face with IC regarding a firefighter injury that occurred earlier. 3113 then went to Admin still covering the District. Released District at 1330 to B31.

Personnel (1) - Unit: 3113

Name	121 - Picard Michael Battalion Chief
Action Taken1	73 - Provide manpower

Unit: 3123

Unit Type	00 - Other apparatus/resource
Dispatch Date/Time	01/22/2010 09:10:52
Enroute Date/Time	01/22/2010 09:10:56
Reflex Time	00:00:04
Priority Enroute	Code 2
Arrival Date/Time	01/22/2010 09:21:28
Travel Time	00:10:32
Response Time	00:10:36
Priority Arrival	Code 2
Cleared Date/Time	01/22/2010 13:55:49
Total Unit Time	04:44:57
Unit Report By	223 - Kurtz Natalie Fire Inspector
Action Taken1	87 - Investigate fire out on arrival
From Quarters	Yes

Narrative

I was dispatched to this incident at 09:10 hours and arrived on scene from quarters at 09:21 hours. My dispatch response was Code 2 and arrival response was Code 2. My primary task performed was fire investigation and the fire was out on my arrival. Prior to my arrival, I made contact with Brian Parker with ATF to see if he was interested in participating in the investigation. He said he was, and would be on scene within thirty minutes.

Upon my arrival I met with the Incident Commander, Battalion Chief Jack Barton, who indicated that the fire originated in the garage of this single-story duet, most likely in the area of the furnace. I waited outside while crews conducted salvage and overhaul, and checked for extension of fire throughout the home and in the attached unit located at 14 Serene Ct., Danville, CA 94526. I coordinated information with Kim French, PIO, and we later worked on loss valuation and press release details and information.

During this time I met with Joan Jordan, the property owner's mother, who told me she had been in the home that day at 07:30 hours to feed

Unit: 3123

the dog. Her daughter, Cristene Mack, was out of town in Southern California and had left the day prior. Mrs. Jordan was taking care of her two young children at her home located at 495 Silver Lake Dr., Danville, CA 94526. When she arrived at the home, she noticed the residence was very warm inside and described it as close to 80-85 degrees. She stated that the home was usually set in the low 70's. She checked the thermostat and it was in the "off" position, yet the furnace continued to run in the garage. She attempted to turn the thermostat down but it would not adjust. She then left the residence. During my interview with Mrs. Jordan I provided her with a copy of an After the Fire Packet.

At approximately 09:45 hours Brian Parker arrived on scene and we began the investigation. We started in the garage area as the front of the home was not easily accessible due to crews continuing with salvage and overhaul. We were able to clearly see the greatest fire damage above the ceiling level directly over the furnace unit. We removed the front of the furnace unit and did not see any fire damage to the inside of the compartment. We checked the top of the unit where the air conditioning unit was located, and did not see any fire damage to the inside of the cooling unit, and all of the copper was undamaged. Brian Parker was able to find part of the heat ducting in the area of the garage, and were able to piece it together. On the front of the sheet metal box duct there was heavy oxidation, a possible indication of extreme heat or exposure to direct flame. After piecing the heat ducting back together, we were also able to see a cut on the heat duct that was most likely done at the time of installation to allow for the two pieces to fit together. There was an obvious gap of a couple of inches that could have allowed for heat to escape this area and have direct contact to the bottom chord of the wood truss. Looking at the bottom of the truss towards the furnace there was little damage to that side of the wood. On the opposite side closest to the furnace there was heavy charring. Considering the home was built in 1973, heat could have been escaping this area for a long period of time, possibly drying the wood and damaging it. Knowing the heater continued to run while the thermostat said it was in the "off" position could possibly indicate the thermostat had failed and the unit continued to run, causing the wood to heat, dry and possibly ignite. I verified with the Town of Danville Building Department that this was the original furnace system, and no permits applications were open.

Brian Parker and I went to the neighboring two-story duet at 14 Serene Ct., Danville and checked the structure. I also made contact with Victor Morrison, Building Inspector, with the Town of Danville Building Department. He evaluated the structural integrity of both homes and reg tagged each home due to weak trusses from fire damage. The tenants of 14 Serene Ct., Danville are Mike and Patience Quinata and their three children. I was able to work with them by ensuring their children were transported home from school, and providing them the After the Fire Packet. I assisted in obtaining clothing and necessary personal items for the family, and coordinated with the board-up company for the restoration of their personal belongings.

At approximately 13:00 hours the owner of 168 Joaquin Dr., Danville, Ms. Cristene Mack, arrived on scene. Chief Barton and I met with her and walked her through the home and described where the fire originated

Unit: 3123

and what the possible cause may have been. She stated that when she left on January 21, 2010 at 07:00 hours in the morning, she noted that the furnace continued to run in the garage even though it was in the "off" position at the thermostat. She then left and went on her business trip to Southern California. I was able to work with Ms. Mack to find and remove several important personal items from her home, and to obtain her child's medications. We were able to remove insurance policy information to assist her and her family.

At 13:55 hours I notified dispatch on my radio that I was clearing the fire scene.

Based upon the fire scene examination, physical evidence, firefighter and witness statements, and the knowledge of fire behavior and development, the fire originated in the garage. The area of origin was in the ceiling area above the furnace. Ignition was the result of a malfunction in the furnace system. The root cause of the malfunction of the furnace system was not determined. This fire was considered accidental, and no further investigation will be conducted by this office.

Personnel (1) - Unit: 3123

Name	223 - Kurtz Natalie Fire Inspector
Action Taken1	87 - Investigate fire out on arrival

Unit: 3131

Unit Type	00 - Other apparatus/resource
Dispatch Date/Time	01/22/2010 09:28:35
Arrival Date/Time	01/22/2010 09:28:39
Response Time	00:00:04
Priority Arrival	Code 2
Unit Report By	304 - French Kimberly Fire Prevention Specialist
Action Taken1	83 - Provide information to public or media
From Quarters	Yes
Narrative	3131 was dispatched to this incident at 09:28 hours. Once on scene I gathered information and prepared a media release. I took calls from local media outlets and provided information to those on scene. Once I returned to quarters I prepared a news story and disseminated it via email and the District's web page.

Personnel (1) - Unit: 3131

Name	304 - French Kimberly Fire Prevention Specialist
Action Taken1	83 - Provide information to public or media

Unit: 3172

Unit Type	00 - Other apparatus/resource
-----------	-------------------------------

Unit: 3172

Dispatch Date/Time	01/22/2010 08:43:50
Enroute Date/Time	01/22/2010 08:43:54
Reflex Time	00:00:04
Arrival Date/Time	01/22/2010 08:46:36
Travel Time	00:02:42
Response Time	00:02:46
Priority Arrival	Code 3
Cleared Date/Time	01/22/2010 11:05:49
Total Unit Time	02:21:59
Unit Report By	252 - Selover James Training Captain
Action Taken1	70 - Assistance, other
From Quarters	No
Narrative	<p>3172 was dispatched to this incident at 08:43 hours. We arrived on scene at 08:46 hours. The primary task performed by our company was to provide assistance.</p> <p>3172 responded from admin., and filled the role of safety officer. Once the incident was stabilized, 3172 cleared the scene and returned to admin..</p>

Unit: 3193

Unit Type	00 - Other apparatus/resource
Dispatch Date/Time	01/22/2010 08:58:01
Enroute Date/Time	01/22/2010 08:58:15
Reflex Time	00:00:14
Priority Enroute	Code 2
Arrival Date/Time	01/22/2010 09:06:18
Travel Time	00:08:03
Response Time	00:08:17
Priority Arrival	Code 2
Cleared Date/Time	01/22/2010 11:25:53
Total Unit Time	02:27:52
Unit Report By	316 - Eberle Chris EMS Specialist
Action Taken1	30 - Emergency medical services, other
Action Taken2	56 - Provide air supply
From Quarters	Yes
Narrative	<p>3193 was dispatched to this incident at 08:58 hours. I arrived on scene at 09:06 hours. My dispatch response was Code 2 and arrival response was Code 2. The primary task performed by our company was emergency medical services. Upon arrival to the scene I began helping</p>

Unit: 3193

setup a rehab area on the sidewalk North of the location. Provided SCBA bottles as well as drinks for responders. Upon arrival of the BS I assisted in switching out bottles, setting up the EZ-UP and chairs to provide Rehab. I was asked by Chief Hart to take pictures for the district. I assisted in watching out for safety on an EMS basis making sure to look for fatigue and possible signs of other injuries. None reported. At 11:25 I was released as crews where in the mop up phase and was not needed further.

Personnel (1) - Unit: 3193

Name 316 - Eberle Christopher EMS Specialist

Unit: B31

Unit Type 92 - Chief officer car
Dispatch Date/Time 01/22/2010 08:34:44
Enroute Date/Time 01/22/2010 08:37:06
Reflex Time 00:02:22
Priority Enroute Code 3
Arrival Date/Time 01/22/2010 08:41:05
Travel Time 00:03:59
Response Time 00:06:21
Priority Arrival Code 3
Cleared Date/Time 01/22/2010 14:14:01
Total Unit Time 05:39:17
Unit Report By 176 - Barton Jack Battalion Chief
Action Taken1 81 - Incident command
From Quarters Yes
Narrative

B31 was dispatched to this incident at 08:34 hours. We arrived on scene at 08:41 hours. We responded from quarters (800 San Ramon Valley Blvd Danville). Our dispatch response was Code 3 and arrival response was Code 3. The primary task performed by our company was incident command.

B31 responded to a report of smoke coming from the eaves of a residence. Upon my arrival E31 and T31 were setting up at a duplex (one residence was single-story, the other was two-story) with smoke coming from several area of the roof structure. A working fire had been declared. E31 was pulling a line and T31 was setting up to go to the roof. E34 arrived and performed recon in the two-story residence.

E31's walk-around put the location of the fire in the attic of the single-story residence. E34 stated that the two-story residence was clear at this time. E31 and E34 initiated fire attack. T31 performed vertical ventilation over the fire. T34 was assigned RIC and secured utilities. E38 was assigned to assist with fire attack and salvage. PM31 stood by and assisted with bottle changes and rehab.

Unit: B31

Significant fire was showing through ventilation opening at two separate locations on the roof indicating substantial spread through the attic. A second alarm was requested.

E32 was assigned to open up the adjoining wall from the two-story residence to check fire extension as the seat of the fire was right up against this wall. E33 was assigned to assist with salvage. E35 was assigned to relieve T31 in order to continue roof operations.

The origin of the fire was over the HVAC unit in the garage. The fire extended into the attic and the void space behind the wall in the garage, between the two attached residences. Significant work was necessary to expose and extinguish that fire. The fire was extinguished and aggressive overhaul salvage work was continued as cellulose insulation was found in the attic, requiring the removal of all of it.

One FF was injured by falling sheet rock.

Salvage and overhaul continued and fire watch was put in place. Upon arrival of the restoration company (Paul Davis), the removal of the insulation was turned over to them. Fire watch was continued until 1730hrs. E31 returned to check the scene at approximately 2100hrs.

Personnel (1) - Unit: B31

Name	176 - Barton Jack Battalion Chief
Action Taken1	81 - Incident command

Unit: BS31

Unit Type	61 - Breathing apparatus support
Dispatch Date/Time	01/22/2010 09:13:05
Enroute Date/Time	01/22/2010 09:13:07
Reflex Time	00:00:02
Arrival Date/Time	01/22/2010 09:16:38
Travel Time	00:03:31
Response Time	00:03:33
Priority Arrival	Code 2
Cleared Date/Time	01/22/2010 11:25:57
Total Unit Time	02:12:52
Unit Report By	323 - Pangelinan Denise Dispatcher
Action Taken1	56 - Provide air supply
From Quarters	Yes
Narrative	The Breathing Support was transported to the scene by Station 32 Crew. Comm Volunteer Ed Ritchie operated the equipment on scene and transported to the unit back to quarters.

Personnel (1) - Unit: BS31	
Name	3157 - Ritchie Edward Comm Volunteer
Unit: E31	
Unit Type	11 - Engine
Dispatch Date/Time	01/22/2010 08:34:41
Enroute Date/Time	01/22/2010 08:37:02
Reflex Time	00:02:21
Arrival Date/Time	01/22/2010 08:39:58
Travel Time	00:02:56
Response Time	00:05:17
Priority Arrival	Code 3
Cleared Date/Time	01/22/2010 13:45:39
Total Unit Time	05:10:58
Unit Report By	73 - Olguin Darren Captain
Action Taken1	11 - Extinguishment by fire service personnel
Action Taken2	12 - Salvage & overhaul
From Quarters	Yes
Narrative	<p>At 08:34 hours on Friday, January 22, 2010 (C-Shift), we responded to a building fire. E31, the first unit to arrive, was on scene at 08:39 hours (Code 3). The last unit cleared the scene at 14:14 hours.</p> <p>The incident occurred at 168 JOAQUIN DR DANVILLE in District 31001. This location can be referenced on map (TB) 653C6. The primary station for this address is 31 (800 San Ramon Valley Blvd Danville).</p> <p>E31 responded to a reported structure fire at 168 Joaquin Dr. E31 arrived to find smoke, light in color and pressure issuing from the attic vent of the one story portion of a duplex unit. A walk around was completed , which found a slider door partially open on the D side of the building. Black smoke was observed in the interior of the home; the smoke was dark, but light in pressure and with very little heat. I entered the home from the rear door and opened the front door for crews attempting to enter.</p> <p>T31 began venting the roof while the interior crews(E34, E31) began pulling ceilings. The interior crews encountered fire along the ceiling which continued over the bathrooms and master bedroom. Once the fire was extinguished, salvage and overhaul operations began. E31 assisted with salvage and overhaul until relieved by E32A.</p>
Personnel (3) - Unit: E31	
Name	73 - Olguin Darren Captain
Name	196 - Treat Jerald Engineer

Personnel (3) - Unit: E31	
Name	294 - Fouts Robert Firefighter/Paramedic
Unit: E32	
Unit Type	11 - Engine
Dispatch Date/Time	01/22/2010 08:52:54
Enroute Date/Time	01/22/2010 08:53:46
Reflex Time	00:00:52
Arrival Date/Time	01/22/2010 09:01:42
Travel Time	00:07:56
Response Time	00:08:48
Priority Arrival	Code 3
Cleared Date/Time	01/22/2010 10:59:20
Total Unit Time	02:06:26
Unit Report By	231 - Blackshear Amelia Captain
Action Taken1	215 - Check for extension
Action Taken2	12 - Salvage & overhaul
From Quarters	No
Narrative	<p>E32 was dispatched to this incident at 08:52 hours. We arrived on scene at 09:01 hours. The primary task performed by our company was to check for extension.</p> <p>E32 responded as part of second alarm structure fire response; Staged.</p> <p>Responded to scene and assigned to adjacent structure, 14 Serene Ct, to check for extension at second story bedrooms. Light smoke noted with heat to walls indicated with TIC. Pulled sheet rock and insulation from walls. Charring noted through to studs. Exposed both bedroom walls.</p> <p>Salvage and overhaul both bedrooms.</p> <p>Released by IC; cleared scene to cover Station 34's zone.</p>
Personnel (3) - Unit: E32	
Name	231 - Blackshear Amelia Captain
Name	270 - Sabye Eric Firefighter/Paramedic
Name	124 - Shaffer Brent Engineer
Unit: E33	
Unit Type	11 - Engine
Dispatch Date/Time	01/22/2010 08:52:54
Enroute Date/Time	01/22/2010 08:54:31
Reflex Time	00:01:37

Unit: E33

Arrival Date/Time	01/22/2010 09:04:14
Travel Time	00:09:43
Response Time	00:11:20
Priority Arrival	Code 3
Cleared Date/Time	01/22/2010 10:44:29
Total Unit Time	01:51:35
Unit Report By	107 - Bradley Scott Captain
Action Taken1	12 - Salvage & overhaul
From Quarters	Yes
Narrative	E33 was dispatched to this incident at 08:52 hours. We arrived on scene at 09:04 hours. We responded from quarters (1051 Diablo Road Danville). The primary task performed by our company was salvage and overhaul. Assigned to interior for salvage. Spread covers in master bedroom and family room. Overhauled family room (pulled ceiling and removed insulation).

Personnel (3) - Unit: E33

Name	107 - Bradley Scott Captain
Name	174 - Stunkel Randy Engineer
Name	163 - Doyle Owen Firefighter

Unit: E34

Unit Type	11 - Engine
Dispatch Date/Time	01/22/2010 08:34:43
Enroute Date/Time	01/22/2010 08:36:38
Reflex Time	00:01:55
Arrival Date/Time	01/22/2010 08:40:53
Travel Time	00:04:15
Response Time	00:06:10
Priority Arrival	Code 3
Cleared Date/Time	01/22/2010 13:17:18
Total Unit Time	04:42:35
Unit Report By	93 - Armario Donald Captain
Action Taken1	10 - Fire control or extinguishment, other
Action Taken2	117 - Stretch Supply line to attack engine
Action Taken3	12 - Salvage & overhaul
From Quarters	Yes
Narrative	E34 was dispatched to this incident at 08:34 hours. We arrived on scene at 08:40 hours. We responded from quarters (12599 Alcosta Blvd San

Unit: E34

Ramon). The primary task performed by our company was to extinguish fire or put under control.

E34 arrived after engine 31, T31 and PM31. Once we arrived, engine 34 took water supply. The myself and Mark Brauer went into the house on Serene Ct. Once inside we did not find any signs of a fire. We did spot heat using the TIC. We poked a hole in the upstairs bedroom sheet rock without finding any fire.

We then went to the other house in the duplex. Once inside, we pulled the sheet rock on the ceiling to expose the fire. Once the roof was opened, we were able to find the fire in the attic and extinguish it. After the fire was out, we helped salvage and over haul.

Personnel (3) - Unit: E34

Name	93 - Armario Donald Captain
Name	195 - Huettis Richard Engineer
Name	99 - Brauer Mark JR Engineer

Unit: E35

Unit Type	11 - Engine
Dispatch Date/Time	01/22/2010 08:52:55
Enroute Date/Time	01/22/2010 08:56:37
Reflex Time	00:03:42
Arrival Date/Time	01/22/2010 09:05:00
Travel Time	00:08:23
Response Time	00:12:05
Priority Arrival	Code 3
Cleared Date/Time	01/22/2010 10:28:47
Total Unit Time	01:35:52
Unit Report By	240 - Ray Alex Captain
Action Taken1	12 - Salvage & overhaul
From Quarters	Yes
Narrative	E35 was dispatched to this incident at 08:52 hours. We arrived on scene at 09:05 hours. We responded from quarters (505 Silver Oak Lane Danville). The primary task performed by our company was salvage and overhaul. We arrived and were assigned to roof division. We assisted in extinguishing the fire.

Personnel (3) - Unit: E35

Name	240 - Ray Alex Captain
Name	205 - Mariolle Matthew Engineer
Name	284 - Smith Shane Firefighter/Paramedic

Unit: E38

Unit Type	11 - Engine
Dispatch Date/Time	01/22/2010 08:34:42
Enroute Date/Time	01/22/2010 08:38:21
Reflex Time	00:03:39
Arrival Date/Time	01/22/2010 08:43:29
Travel Time	00:05:08
Response Time	00:08:47
Priority Arrival	Code 3
Cleared Date/Time	01/22/2010 10:25:39
Total Unit Time	01:50:57
Unit Report By	90 - Colon James Captain
Action Taken1	112 - Stretch 1 ½" or 1 ¾" line, extinguish fire
Action Taken2	12 - Salvage & overhaul
From Quarters	Yes
Narrative	<p>E38 was dispatched to this incident at 08:34 hours. We arrived on scene at 08:43 hours. We responded from quarters (1600 Bollinger Canyon Road San Ramon). The primary task performed by our company was to stretch 1 ½" or 1 ¾" line and extinguish fire.</p> <p>E38 crew extended 1.75" LL from E31 to garage to extinguish attic fire. E38 crew assisted with salvage and overhaul. During overhaul a large piece of wet sheet rock fell from ceiling in garage and hit FF Ybarra in head. Ybarra had Head, Neck, Back and Shoulder pain and was sent to Kaiser Antioch for evaluation and treatment. Captain Colon discovered a dog behind during salvage. Engineer Tidd rescued the the dog and returned the dog to it's owners.</p>

Personnel (3) - Unit: E38

Name	90 - Colon James Captain
Name	147 - Tidd Tracy Engineer
Name	192 - Ybarra Michael Firefighter/Paramedic

Unit: PM31

Unit Type	76 - ALS unit
Dispatch Date/Time	01/22/2010 08:34:43
Enroute Date/Time	01/22/2010 08:37:13
Reflex Time	00:02:30
Arrival Date/Time	01/22/2010 08:42:25
Travel Time	00:05:12
Response Time	00:07:42
Priority Arrival	Code 3

Unit: PM31

Cleared Date/Time	01/22/2010 10:45:51
Total Unit Time	02:11:08
Unit Report By	255 - Avery Steve Firefighter/Paramedic
Action Taken1	201 - Operated/Assigned as RIC
From Quarters	Yes
Narrative	PM31 was dispatched to this incident at 08:34 hours. We arrived on scene at 08:42 hours. PM 31 was assigned IRIC. See other narratives for more info.

Personnel (2) - Unit: PM31

Name	182 - Archuleta John Firefighter/Paramedic
Name	255 - Avery Steve Firefighter/Paramedic

Unit: T31

Unit Type	12 - Truck or aerial
Dispatch Date/Time	01/22/2010 08:34:41
Enroute Date/Time	01/22/2010 08:37:07
Reflex Time	00:02:26
Arrival Date/Time	01/22/2010 08:40:50
Travel Time	00:03:43
Response Time	00:06:09
Priority Arrival	Code 3
Cleared Date/Time	01/22/2010 12:08:07
Total Unit Time	03:33:26
Unit Report By	151 - Avery Michael Captain
Action Taken1	51 - Ventilate
Action Taken2	215 - Check for extension
Action Taken3	12 - Salvage & overhaul
From Quarters	Yes
Narrative	<p>T31 was dispatched to this incident at 08:34 hours. We arrived on scene at 08:40 hours. We responded from quarters (800 San Ramon Valley Blvd Danville). The primary task performed by our company was ventilation.</p> <p>T31 responded with the above listed assignment to a reported structure fire. Upon arrival, we were assigned vertical ventilation. After completion, we checked for extension in the uninvolved unit, then assisted with salvage and overhaul in the involved unit and on the roof. We assisted with putting units back in service and were released by the IC. T31 cleared.</p>

Personnel (3) - Unit: T31

Name	151 - Avery Michael Captain
Name	133 - Jannisse Paul Engineer
Name	227 - Thomas Todd Firefighter/Paramedic

Unit: T34

Unit Type	12 - Truck or aerial
Dispatch Date/Time	01/22/2010 08:34:42
Enroute Date/Time	01/22/2010 08:37:20
Reflex Time	00:02:38
Priority Enroute	Code 3
Arrival Date/Time	01/22/2010 08:41:25
Travel Time	00:04:05
Response Time	00:06:43
Priority Arrival	Code 3
Unit Report By	136 - Bailey Dale Captain
Action Taken1	201 - Operated/Assigned as RIC
Action Taken2	12 - Salvage & overhaul
From Quarters	Yes
Narrative	<p>T34 was dispatched to this incident at 08:34 hours. We arrived on scene at 08:41 hours. We responded from quarters (12599 Alcosta Blvd San Ramon). Our dispatch response was Code 3 and arrival response was Code 3. The primary task performed by our company was to Operate/Assigned as RIC.</p> <p>T34 responded code three for a structure fire at 168 Joaquin Dr.. Upon arrival, we were assigned RIC by IC. We later assisted with overhaul and then cleared.</p>

Personnel (3) - Unit: T34

Name	136 - Bailey Dale Captain
Name	144 - Curtis Daniel Engineer
Name	225 - Balch Scott Firefighter/Paramedic

Persons Involved (1)

Name	MS Cristene Mack
Responsible for address	Yes
Involvement	Property Owner
Address	168 JOAQUIN DI
Incident Address	Yes
City, State ZipCode	DANVILLE, CA 94526

Fire

Residential Units	1
Buildings Not Involved	Yes
Acres Burned	None
Area Of Origin	47 - Vehicle storage area; garage, carport
Heat Source	10 - Heat from powered equipment, other
Item First Ignited	UU - Undetermined
Confined To Object Of Origin	Yes
Cause of Ignition	3 - Failure of equipment or heat source
Factor Contributing To Ignition1	22 - Manual control failure
Human Factor	None
Suppression Factor	None
Equipment Involved Type	100 - Heating, ventilation and air conditioning, other
Equipment Involved Power	21 - Natural gas or other lighter-than-air gas
Equipment Involved Portability	2 - Stationary
Mobile Property Involved	None

Structure

Structure Type	1 - Enclosed building
Building Status	2 - In normal use
Floors Above Grade	1
Floors Belows Grade	0
Building Length	25
Building Width	30
Story of Fire Origin	1
Fire Spread	4 - Confined to building of origin
Construction Class	6 - Frame (Construction Class 6)
Roof Covering	2 - Composition Shingles
Building Type	R3 - Dwelling, lodging house, family residence
Smoke Spread	3 - Confined to building of origin
Fire Alarm Notification	4 - Smoke detector
Detector Presence	1 - Present
Detector Type	1 - Smoke
Detector Power	1 - Battery only
Detector Operation	U - Undetermined
AES Presence	N - None Present
Stories Minor Flame	0

Structure

Stories Significant Flame	0
Stories Extreme Flame	1
Stories Extreme Smoke	1
Stories Heavy Water	1

